



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
MYRTLE ROAD	o/s 195-197	TR: Felling	Extensive kerb disruption	Prunus sp	Plant in new 800 pit o/s-between 195 - 197, (same as old tree)	Pyrus calleryana 'Chanticleer'
MYRTLE ROAD	o/s 207-209	TR: Felling	Kerbs disrupted, unable to repair without damage to roots	Sorbus aria	Plant in new 800 pit o/s-between 207 - 209, (same as old tree)	Pyrus calleryana 'Chanticleer'
MYRTLE ROAD	o/s 187-189	TR: Felling	Kerbs displaced and f/w damaged	Prunus sp	Plant in new 800 pit o/s-between 187 - 189, (same as old tree)	Pyrus calleryana 'Chanticleer'
MYRTLE ROAD	o/s 157 to 159	TR: Felling	F/W uplifted and damaged, kerb displaced	Prunus sp	Plant in new 800 pit o/s-between 157 - 159, (same as old tree)	Pyrus calleryana 'Chanticleer'
MYRTLE ROAD	o/s 155	TR: Felling	Kerbs displaced and f/w disrupted, roots will be damaged upon reconstruction	Prunus sp	Plant in new 800 pit o/s-between 153 - 155, (same as old tree)	Pyrus calleryana 'Chanticleer'